

A diver in a yellow helmet and black wetsuit is working underwater. The diver is holding a tool and is positioned near a rocky structure. The background is a deep blue underwater environment.

Discover the
AMS difference

Content

1 Our Mission, Vision & Commitment

2 Future Prospects

3 Management Team

4 Our Services

Marine/Ship Maintenance

Topside/Underwater Services

Steel Fabrication/Engineering

Other Services

5 Quality, Occupational Health & Safety Policy

6 Appendix

Track Record

Our Mission, Vision & Commitment

Advantage Marine Services (Malaysia) Sdn Bhd was established in March, 2014 to provide top notch/high quality in water services for marine/shipping and offshore. We are committed to provide services that are identified with best-in-class safety, quality and cost effectiveness.

To be a leading world-class underwater inspection and steel fabrication specialist.

OUR VISION

To provide
best-in-class diving
equipment
combined with
OGP/IMCA
standard, practices
and procedures.

OUR COMMITMENT

Our Businesses

- CLASS Survey (ABS, DNV/GL, BV, LRS, NKK, etc)
- Ship Husbandry Services – Hull Cleaning, Propeller Polishing, etc
- Afloat Repair Services – Underwater Hull Repairs
- NDT Works
- Fabrication, Piping & Steel Renewal
- Accommodation Upgrading (Carpentry / Architectural work)
- Electric Repairs (Air Conditioning, Motor Rewinding)
- HVAC, Control Solution

Our Mission

- To deliver safe, professional and efficient operations even for the most demanding jobs.
- To apply innovative and systematic approaches to ensure consistent delivery and satisfaction to our clients.
- To continue searching for alternatives to enhance performance of customer operation.
- To adhere to Ethical and Offshore Standards in fulfilling assignments and requirements of the undertaken job.
- To build long term relationships with clients and vendors.



Advantage Marine Services (Malaysia) Sdn Bhd provides 24/7 underwater operations within the Southeast Asia Countries.



Future Prospects

Management Team

DIRECTOR
Andrew Teow



Mr Andrew Teow joined AMS in April 2016. He graduated with Bachelor Degree (Honours) and Master Degree in Petroleum Engineering from University of Technology Malaysia, Johor Bahru, Malaysia.

He has over 15 years of experiences in oil and gas encompassing the drilling operations, solids control and waste management, sales and marketing and business development with different International Service Companies. In addition, he also has 5 years experiences working with manufacturing/automotive industry working as the Technical Support Engineer overseeing manufacturing processes, quality of various products, meeting production yield and deadlines as set by clients.



Before joining AMS, he was formerly with a leading international drilling company for 12 years with his last designation as Drilling Superintendent to look after an ultra-deep water drilling rig with excellent safety record/achievements. In addition, he has had work experiences across the SEA region where he was involved in managing various sizable projects with up to RM 100 million in value.

With his leadership, experiences and networking, AMS has diversified and expanded into steel fabrication, accommodation upgrading, engineering controls and solutions to support clients' needs and operations.

GENERAL MANAGER
Victor Wong



Mr Victor Wong graduated in 1985 with a Degree in Business Administration and has worked in the financial industry in Singapore for 10 years before entering the marine industry in 2002. He has been in a management role in a leading marine company helping grow the business from start up to a company with excess of 100 permanent staff. He has also been involved in starting up new businesses in Malaysia and Singapore.



Marine / Ship Maintenance

- Hull cleaning/propeller polishing by hydraulic power-pack and brush-kart
- Underwater Hull repair by cofferdam
- Class In-water surveys/UWILDs, rudder pintle clearances, tail shaft wear-down measurements
- Salvage works
- Full range of other underwater maintenance services



Topside / Underwater Services

- Class UWILD Inspection for Rig or Platform
- NDT Rope Access Inspection / Repair
- NDT inspection / Hull or Pipe Thickness Gauging (Rope access and Ground work)
- HP jetting services





Steel Fabrication / Engineering

- Engineering support inclusive design / Calculation analysis / PE endorsement
- Workshop steel fabrication (cantilever platform, boom rest, piping, high pressure piping, container, etc)
- Site survey, site installation and site repair
- Manpower supplier for inshore or offshore (Fitter, Welder, Rope access personnel, Rope access inspector, PCN inspector, electrician and so on)
- Plant shut down maintenance works



Other / General Services

- Accommodation upgrading / Carpentry work
- High Pressure Water Blasting and painting (Rope Access & Ground work) HVAC
- Control Solution / Automation (Calibration for all sensors and gauges - such as fire, gas, wind speed, humidity, pressure and etc)
- Testing & commissioning on machinery & other newly installed facility such as lifeboat
- Jetty construction activities by diver
- HVAC
- Trading
- Logistic
- Automation



Quality, Occupational Health & Safety Policy

Statement of Policy

Advantage Marine Services (Malaysia) Sdn Bhd specializes in In-water Services for Marine, Shipping and Offshore including Structural Steel Fabrication and Trading Activities. We are committed to both our customers and shareholders, as we will continually improve the work process in delivering the right solutions and dependable services to our customers.

We aim to provide our customers with high-level quality products and services meeting contractual and regulatory requirements while demonstrating sound health, safety and environmental performance. The products and services we offered are fit for its intended purposes, at the same time promote and maintain the highest degree of health and safety of our employees, subcontractors and visitors at our workplace including prevention of environmental pollution.

The company's activities are sufficiently controlled to prevent injury and ill health as well as to protect the health & safety of our employees, freelancers and visitors including property from all health & safety risks that can be reasonably expected. We establish appropriate operational control to mitigate any significant environmental aspect.

We utilize ISO 9001, ISO 14001 & OHSAS 18001 Standards to develop our Management System in order to help us achieve our business goals via:

Attain Customer Satisfaction

Maintain Competent Resources

Sustainable Business Model

Compliance to Legal and Other Requirements

Achieve Management System Outputs

Reduce or prevent environmental pollution

Eliminate injury and ill health

Quality, Occupational Health & Safety Policy

A team of competent workforce will execute our deliverables. This policy is communicated to employees and those working for and on behalf of the company, and is made available to interested parties. Employees shall be made aware of the policy and objectives, their contribution towards the achievement of the policy. The policy shall be reviewed by the Management Team at periodic intervals to ensure it remains relevant, suitable, adequate and effective in meeting the business needs of the company.

Objectives

AMS's objectives in the fulfillment of this policy are:

- To be an industry leader in Quality, Health, Safety and Environment (QHSE),
- To give occupational health & safety and environmental considerations equal importance as quality, morale, cost and production,
- To start work only with confirmation that essential safety systems are in place, and if safety would be compromised, operations are to be suspended,
- To only accept safe acts within the work of any AMS employee or other person working on any worksite, facility, vessel or rig,
- To provide appropriate levels of healthcare and rehabilitation for all EMPLOYEES,
- To promote an excellent Quality, Health and Safety, and Environment culture within the organization by means of information sharing, by including personnel in decision making and by delegating specific Quality, Health and Safety Management functions,
- To have all personnel recognize their responsibility to identify and eliminate hazards, control risk, and prevent injury to themselves and others as well as identify environmental aspect and determine actions to mitigate environmental impacts,
- To ensure Third Party Personnel clearly understand and adhere to AMS's quality, occupational health & safety and environmental policy and standards, and where necessary, assist in achieving them, and
- To provide leadership and training for all employees in following safe operating procedures and in developing safe work attitudes.



Appendix

Track Record

COMPANY TRACK RECORD

No	Date	Vessel Name	Operation	Ship Type	GRT	Location
477	27.11.19	FSU 1	Shop Fabricate and Site Installation of Ladder for FSU 1 at MMHE	Tanker	80510	MMHE
476	27.11.19	MV SINAR JEPARA	MV SINAR JEPARA IWS Pasir Gudang Anchorage	Container Ship	4632	Pasir Gudang Anchorage
475	27.11.19	na	Supply 1 STOPPAG Rep for QA purpose on Shell Installation	na	na	MIRI Offshore
474	23.11.19	FSU 1	GS & Ballast Priming Pipe Renewal for FSU 1 at MMHE	Tanker	80510	MMHE
473	23.11.19	MT Chios Star	MT Chios Star Underwater Photography Stern Seal at PTP Anchorage Malaysia	Crude Oil Tanker	29528	PTP Anchorage
472	14.11.19	Golden Dowa Myanmar	Supply Power Cable And Ex Proof Hubble Lights	na	na	Myanmar
471	11.11.19	Floatel Triump	Shop fabricate of 10 x 8 inch pipe spool for Floatel Triumph	Accommodation Platform	27211	AMS Workshop
470	11.11.19	FSU 2	Deck Compressed Air Wasted Pipe Renewal for FSU 2	Tanker	80510	Melaka
469	10.11.19	Southern Reverence	Southern Reverence Rudder inspection at Tanjung Pelepas (Malaysia)	Crude Oil Tanker	60855	PTP Anchorage
468	9.11.19	NAUTICA MAHARANI	NAUTICA MAHARANI Loa 120M Hull Cleaning Melaka	Tanker	7591	Melaka ANchorage
467	8.11.19	MV Ela	M/V Ela: Speed Log Replacement OPL Port Klang	General Cargp	1345	Port Klang
466	8.11.19	MT NORDIC APOLLO	MT NORDIC APOLLO HULL CLEANING PROPELLER POLISHING LINGGI	Crude Oil Tanker	81310	Linggi Melaka
465	6.11.19	Seri Alam	Seri Alam Underwater Inspection and Propeller Polishing Bintulu Anchorage	LNG Tanker	95729	Bintulu Anchorage
464	6.11.19	Nautika Renggam	Nautika Renggam Underwater Inspection Johor OPL ETA 7 Nov	Oil/Chemical Tanker	7057	Pasir Gudang Anchorage
463	4.11.19	Vlcc E MEI SAN	Vlcc E MEI SAN Hull Cleaning PTP Anch	Crude Oil Tanker	163882	PTP Anchorage
462	1.11.19	Davis Sea	Davis Sea Underwater Hull Cleaning Tanjung Pelepas (PTP) Malaysia ETA 3 Nov	Crude Oil Tanker	57164	PTP Anchorage



461	30.10.19	E5006	To supply 10 Roll Plastic Wrapping black color for Ensco E5006	Semisubmersible	-	Johor Port
460	30.10.19	E5006	To supply Jumbo Bag for Ensco E5006	Semisubmersible	-	Johor Port
459	29.10.19	Puteri Nilam Satu	Puteri Nilam 1 Underwater Inspection and Propeller Polishing Bintulu Anchorage Oct	LNG Tanker	94446	Bintulu Anchorage
458	25.10.19	Hilong 106	To supply Scaffolding Materials for Hilong 106 (Bangladesh Project)	Pipe Laying Barge	-	Johor Port
457	25.10.19	E5006	To supply Wooden Pallet for Ensco E5006	Semisubmersible	-	Johor Port
456	23.10.19	Wharf site	Hydrographic survey at front of existing THHE wharf 2500Mt, Pulau Indah, Selangor	-	-	TH Heavy
455	23.10.19	Bibby Renaissance	LR In Water Survey for Barge Accommodation Bibby Renaissance at Johor Port	Accommodation Barge	12356	Johor Port
454	23.10.19	FSU 1	Spare Part Replacement for 15ppm bilge Alarm Monitor for Tenaga Satu	Tanker	80510	Melaka
453	22.10.19	Lerici	Lerici Engine Room Ventilation Survey at Bintulu	LNG Tanker	46555	Bintulu
452	22.10.19	Portovenere	LNG Portovenere UW Echo Sounder Replacement works Bontang Indonesia	LNG Tanker	46555	Bontang , Indonesia
451	22.10.19	Portovenere	Portovenere Engine Room Ventilation Survey in Bontang	LNG Tanker	46555	Bontang , Indonesia
450	22.10.19	Ensco 5006	BELT-DRIVE,GULF GULP,CBD880-30,COGGED DRIVE,208V 60HZ,(HAWK 524918116)	Semisubmersible	-	Johor
449	15.10.19	Puteri Nilam	Puteri Nilam Underwater Inspection and Propeller Polishing Bintulu Anchorage Oct	LNG Tanker	86211	Bintulu Anchorage
448	9.10.19	E5006	Supply Carton Box Ensco	Semisubmersible	-	Johor Port
447	7.10.19	TB Ruby	TB Ruby Underwater Survey and Spot Cleaning OPL Tanjung Pelepas Johor Malaysia ETA 10 Oct	Craft	-	Port Klang ANchorage
446	4.10.19	FSU 2	Fabricate Additional Gear Rack in LO Store for FSU 2	Tanker	80510	Melaka



445	4.10.19	LNGC Seri Bijaksana	Seri Bijaksana Underwater Inspection and Propeller Polishing Bintulu Anchorage Oct	LNG Carrier	104881	Bintulu Anchorage
444	27.9.19	Floatel Triump	Installation of Air Compressor for Floatel Triumph	Accommodation Platform	27211	Johor Anchorage
443	24.9.19	Puteri Zamrud	Supply Habitat System for LNG vessel_Puteri Zamrud in Bintulu Anchorage	Tanker, Hazardous D	94446	Bintulu Anchorage
442	20.9.19	EM Vitality	EM Vitality Underwater Inspection at Melaka Anchorage	Oil Tanker	3828	Melaka ANchorage
441	16.9.19	E8504	Supply 2 Engineer for E8504 Site Survey at Labuan Anchorage	Semisubmersible	-	Labuan Anchorage
440	14.9.19	Aman Sendai	Aman Sendai Underwater Survey Prior Drydock Bintulu Malaysia	LNG Vessel	16336	Bintulu Offshore
439	10.9.19	Hilong 106	Sea Water Pipes of E/R (Rev 9) for Hilong 106 at Johor Port	Pipe Laying Barge	-	Johor Port
438	4.9.18	PP101	To Shop Fabricate Pipe Spool for Diverter Fill Line for PP101	Jack Up Rig	-	workshop
437	3.9.19	New Global	New Global Spot Cleaning & Class LR In Water Survey PTP Malaysia	Tanker	159016	PTP Anchorage
436	2.9.19	Hilong 106	Deck Generator Overhaul for Hilong 106 at Johor POrt	Pipe Laying Barge	-	Johor Port
435	30.8.19	FSU 1 & FSU 2	Pre-IWS for FSU 1 and FSU 2	Tanker	80510	Linggi Melaka
434	28.8.19	Darin Star	UNDERWATER BLANKING OF SEA CHEST LINGGI MALAYSIA	Tanker	158475	Linggi Melaka
434	20.8.19	MCC Chittagong	MCC Chittagong Underwater Rope Removal at Bow Thruster @ Port Klang Malaysia	Container Ship	31649	Port Klang
433	20.8.19	Kalamoti Trader	Diving inspection of BT at Port Klang OPL	Cargo Ship	25145	Port Klang Anchorage
432	20.8.19	Fortune Star	Fortune Star Spot Cleaning UWILD Class LR Kuala Linggi Melaka	Cargo	9575	Linggi Melaka
431	15.8.19	PP101	Fabricate and Installation of Drag Chain Tray for BOP Hoist onboard PP101	Jack Up Rig	-	Johor Port
430	15.8.19	FSU 2	To Supply SS316 suction strainer spacer for FSU 2	Tanker	80510	Linggi Melaka



429	15.8.19	FSU 1 / FSU 2	To Provide Service to Calibrate and Issue Certificate Dewpoint Digital Meter for Tenaga Satu	Tanker	80510	Linggi Melaka
428	11.8.19	PVD 1	Seabed Survey for PVD1 at Offshore Sabah	Jack Up Rig	-	Labuan Offshore
427	8.8.19	COSL POWER	Intermediate UWILD for COSL Power	Jack Up	-	Surabaya Offshore
426	7.8.19	FSL London	FSL London IWS NK Class Pasir Gudang Malaysia	Tanker	11587	Johor Port
425	3.8.19	PP101	To Supply Welder and Consumable for AISI 4130 Welding onboard PP101	Jack Up Rig	-	Johor Port
424	1.8.19	Bellatrix-1	Bellatrix-1 Underwater Rope Removal for Bow Thruster @ Tanjung Pelepas ETA 3/08	Cargo	34610	PTP ANchorage
423	29.7.19	PP101	TO supply 3 pax General Worker to PP101	Jack Up Rig	-	Johor Port
422	26.7.19	Sea Coral	Sea Coral: Sea chests/ Echo sounder/ Speed log/ ICCP anodes & reference cell cleaning	Tanker	156802	PTP ANchorage
421	24.7.19	FSU 1/FSU 2	To Provide Service to Calibrate and Issue Certificate for 15ppm bilge Alarm Monitor (Tenaga Empat)	Tanker	80510	Linggi Melaka
420	22.7.19	New Spring	Oil Tanker UWILD Class CCS Port Linggi Malaysia - DM	Tanker	80510	Linggi Melaka
419	22.7.19	Sapura Jane	Shop Fabricate and Installation of Various Platform for Sapura Jane and Tank Cleaning	DP Class 2 Diving Suppoer and ROV Vessel	3389000	Workshop and Johor Port
418	22.7.19	FSU 2	Renewal of IGG Steam Waste Pipe Vent Penetration Pipe at Poop Deck for FSU 2	Tanker	80510	Melaka
417	17.7.19	Marine Star	Marine Star TBN MCC Chittagong Spot Cleaning & Class LRS In Water Survey PTP	Tanker	158475	PTP anchorage
416	12.7.19	Monaco	Monaco In Water Survey (DNVGL) at Port Klang, Malaysia	Container Ship	214286	Port Klang ANchorage
415	4.7.19	Nautica Maharani	UWILD for Nautica Maharani at Melaka Anchorage	Tanker	7591	Melaka
414	27.6.19	Ocean Galaxy	OCEAN GALAXY - UWILD under Class NK Johor Port	Cargo Ship	22662	Johor Port



413	25.6.19	Trim System	16bottle gas rack with bottle fro Trim System	-	-	Trim System
412	25.6.19	Cape Araxos	Cape Araxos Class DNVGL UNDERWATER INSPECTION Port Klang OPL Malaysia	Cargo Ship	25165	Port Klang OPL
411	20.6.19	MS 1	Supply Scaffolder and Welder to Ms 1	Semisubmersible	-	Labuan Anchorage
410	3.6.19	Puteri Delima Satu	Puteri Delima Satu PreDocking Underwater Inspection at Bintulu Offshore	LNG Tanker	94430	Bintulu ANchorage
409	28.5.19	PP101	Anode installation by RA for PP101 at Johor Port	Jack Up Rig	-	Johor Port
408	28.5.19	PP101	Jetting Line Repair for PP101 at Johor Port by RA Team	Jack Up Rig	-	Johor Port
407	23.5.19	FSU 2	Design, Fabricate and Install Various Store Room Vent Flap for FSU 2	Tanker	80510	Melaka
406	23.5.19	FUS 1	Design, Fabricate and Install Various Store Room Vent Flap for FSU 1	Tanker	80510	Melaka
405	23.5.19	CS Pioneer / EM Splendor	EM SPLENDOR Loa 334 Full Hull Cleaning PTP	Tanker	154159	PTP Anchorage
404	23.5.19	Ensco 106	TO Supply Welding CONsumables ENSco 106	Jack Up Rig	-	Indonesia
403	22.5.19	PVD 3	ABS UWILD for RIG PVD 3 at KSB Anchorage	Jack Up Rig	-	KSB ANchorage
402	22.5.19	PVD 3	PVD 3 Side Scan Sonar, Single Beam Echo Sounder and Sub Bottom Profiling survey 200 x 200 at KSB Anchorage	Jack Up Rig	-	KSB ANchorage
401	21.5.19	FSU 2	Portable Lifting Gear Inspection and Certification for FSU 2	Tanker	80510	Melaka
400	21.5.19	FSU 1	Portable Lifting Gear Inspection and Certification for FSU 1	Tanker	80510	Melaka
399	20.5.19	NYK Athena	NYK Athena Loa 299M Class NKK Inspection Port Klang OPL	Container Ship	75484	Port Klang OPL
398	20.5.19	PP101	UWILD at Johor Port	Jack Up Rig	-	Johor Port
397	15.5.19	Maribo Maersk	Maribo Maersk- Take out sensors in SB rudder-TPP-17 May	Container Ship	194849	PTP Wharf



396	14.5.19	Seri Camar	Underwater Hull Paint Inspection for Seri Camar	LNG Tanker	133948	Bintulu anchorgae
395	10.5.19	FSU 1	Fabricate 2 Spare Gear Rack and Modification of 2 nos Opening on Deck for FSU 1	Tanker	80510	Melaka
394	9.5.19	FSU 2	Meat Room Door and Frame Replacement for FSU 2	Tanker	80510	Melaka
393	9.5.19	FSU 1	Fish Room Door and Frame Replacement for FSU 1	Tanker	80510	Melaka
392	9.5.19	MS 1	To Supply Radio Standard Horizon to MS 1	Semisubmersible	-	Labuan
391	9.5.19	NAUTICA BATU PAHAT	NAUTICA BATU PAHAT Propeller inspection, Manual Cleaning & Clearing of Entanglement Melaka Anch	Oil Tanker	7591	Melaka Anchorage
390	8.5.19	MV WHITE LILY	MV WHITE LILY Loa 110m Class NK IWS Pasir Gudang	Cargo SHip	7514	Johor Port
389	8.5.19	SEA VENUS	UW Inspection / Clearing or ENTanglement Propeller or rudder Kukup Anch Malaysia	Bulk Carrier	44025	PTP Anchorage
388	7.5.19	E106	Uwild - Top Side survey by Rope Access for Ensco 106-PNG	Jack Up Rig	-	Indonesia
387	4.5.19	E106	SUPPLY EH 36 plate to EN 106	Jack Up Rig	-	Indonesia
386	30.4.19	Seri Begawan	Supply Habitat System for LNG vessel_Seri Begawan for the Aluminium Ladder Welding in Melaka Anchorage	LNG Tanker	105335	Melaka
385	25.4.19	FSU 2	Design, Fabricate and Install Various Store Room Vent Flap for FSU 2	Tanker	80510	Melaka
384	25.4.19	FSU 2	Fabricate 2 Spare Gear Rack and Modification of 2 nos Opening on Deck for FSU 2	Tanker	80510	Melaka
383	25.4.19	FSU 2	Boiler Condensate Heating Pipe Line Repair and Renewal of Port Boiler Pressure Gauge for FSU 2	Tanker	80510	Melaka
382	25.4.19	FSU 2	Funnel Scupper Drain Pipe Renewal for FSU 2	Tanker	80510	Melaka
381	25.4.19	FSU 2	To Supply & Machine Brass Spray Nozzle to FSU 2	Tanker	80510	Melaka
380	25.4.19	FSU 1	To Supply & Machine Brass Spray Nozzle to FSU 1	Tanker	80510	Melaka



379	24.4.2019	MS 1	Supply of Hempel Paints for Ensco MS 1	Semisubmersible	-	Ex AMS Workshop
378	24.4.2019	MS 1	Supply of Hempel Paints for Ensco MS 1	Semisubmersible	-	Ex AMS Workshop
377	19.4.19	BTS CHRISTINA	BTS CHRISTINA Class DNVGL CCTV inspection at Pasir Gudang	Oil Tanker	7678	Pasir Gudang Anchorage
376	10.4.19	PVD 1	PVD 1 Side Scan Sonar, Single Beam Echo Sounder and Sub Bottom Profiling survey 200 x 200 at Labuan Anchorage	Jack Up Rig	-	Labuan Anchorage
375	8.4.19	LNG GASELYS	GASELYS LOA 289M BV Intermediate Survey Pasir Gudang Anch	LNG Tanker	97741	Pasir Gudang Anchorage
374	27.3.19	FSU 1	Crew Mess Wash Basin and Rack Upgrading for FSU 1	Tanker	80510	Melaka
373	22.3.19	Seri Cemara	Seri Cemara Underwater Plugging Tompok Utara	Tanker	133948	Pasir Gudang Anchorage
372	19.3.19	Nipa	Nipa Loa 279M propeller and sea chest cleaning	Tanker	152680	PTP Anchorage
371	11.3.19	Tg Bin	Provide Valeport 106 for rental and 2 x brackets	-	-	Tg Bin
370	10.3.19	WORKSHOP	Fabricate Hydraulic BrushCart	-	-	-
369	7.3.19	Puteri Firus Satu	Puteri Firus Satu//Under Water Inspection & Propeller polish in Bintulu	Tanker, C	94446	Bintulu ANchorage
368	7.3.19	Grace Star	Grace Star Class LRS In Water Survey PTP	Tanker	163761	PTP Anchorage
367	5.3.16	Sentosa Trader	Sentosa Trader// UW cleaning Port Klang OPL	Container Ship	13764	POrt Klang Anchorage
366	5.3.19	FSU 2	New AC Cooling Water Emergency Supply for FSU 2	Tanker	80510	Melaka
365	5.3.19	New Global	Funnel Company Logo Re-Branding for New Global at PTP Anchorage	Tanker	159016	TBA
364	4.3.19	Ensco 115	Supply Mixed Hard Wood for Ensco 115 to Johor Port	Jack Up	-	Johor Port
363	1.3.19	No vessel name	Cable Landing Support Works Senibong	-	-	Senibong Johor
362	28.2.19	FSU 1 & FSU 2	Pre-IWS for FSU 1 and FSU 2	Tanker	80510	Melaka



361	28.2.19	Seri Bakti	BKT19/DD-SA - Underwater Hull Inspection/BKT19XXXX Melaka	Tanker	105335	Melaka
360	28.2.19	Winson 5	Winson No.5: Underwater inspection CLASS ABS	Tanker	163761	PTP Anchorage
359	28.2.19	FSU 2	Cargo Pipe Support (H Beam) Refurbishment for FSU 2	Tanker	80510	Melaka
358	28.2.19	FSU 2	Swimming Pool Drain Pipe Renewal for FSU 2	Tanker	80510	Melaka
357	26.2.19	FSU 2	IGG Room Main Fire Line Piping for FSU 2	Tanker	80510	Melaka
356	22.2.19	Hilong 106	Calibrate Fuel oil flowmeter for Hilong 106 at Johor Port	Pipe Laying Barge	-	Johor Port
355	22.2.19	X-PRESS GANGES	X-PRESS GANGES Underwater Inspection at Port Klang under KR Class	Cargo	8971	Port Klang Anchorage
354	20.2.19	West Orion	Underwater Inspection for 11nos Anchors for West Orion at West Wharf KSB	Semisubmersible	-	KSB West Wharf
353	20.2.19	West Wharf	Jetty Underwater Inspection at West Wharf KSB	-	-	KSB West Wharf
352	20.2.19	Hilong 106	HILONG 106 Loa 169m Class ABS UWILD Johor Malaysia	Pipe Laying Barge	-	Johor Port
351	19.2.19	Mopu Sepat	Mopu Sepat Leg Cutting	Semisubmersible	-	KSB West Wharf
350	19.2.19	MS 1	Supply NDT personnel for MS1	Semisubmersible	-	Labuan Anchorage
349	19.2.19	Epic Marine	PVD 2 Side Scan Sonar, Single Beam Echo Sounder and Sub Bottom Profiling survey 200 x 200 at KSB Anchorage	-	-	KSB Anchorage
348	18.2.19	Sevan Driller	Supply Signal Flare, First Aid Kit and Buoyant rescue quoit for Sevan Driller	Semisubmersible	-	Ksb East Wharf
347	18.2.19	Ensco 115	Accommodation Toilet Repair for Ensco 115 at Johor Port	Jack Up	-	Johor Port
346	15.2.19	Boat SAFIR KISH 4	Re-Activation of the vessel here in Sijangkang, Teluk Panglima Garang, Selangor	-	-	Teluk Panglima Garang, Selangor
345	11.2.19	PUTERI INTAN SATU	Puteri Intan Satu Propeller Polishing Bintulu (from Seocean Diving)	Tanker	94430	Bintulu Anchorage
344	13.2.19	Seri Angkasa	MISC Seri Angkasa Propeller Polishing and IWS Bintulu	Tanker	95729	Bintulu Anchorage



343	8.2.19	Sea Coral	SEA CORAL UW Repairs by Belzona	Tanker	156802	PTP Anchorage
342	8.2.19	MS 1	Supply of Teepol Coumpount Detergent for MS 1	Semisubmersible	-	Labuan
341	7.2.19	Sevan Driller	Supply RA Team for the Tower Gangway Removal for Sevan Driller at East Wharf, KSB	Semisubmersible	-	KSB East Wharf
340	7.2.19	MV SENDOM	UWI, Clearing Entanglement, Option HC	Cargo	31144	Johor Anchorage
339	1.2.19	Hilong 106	Motor Rewinding for Hilong 106	Pipe Laying Barge	-	Johor Port
338	1.2.19	MS 1	Rental of 10unit IBC Tank wit 2 certified basket for MS 1	Semisubmersible	-	Labuan
337	29.1.19	MT HErcules	Mv HERCULES 1 CCTV Inpection, HC, PP, SC Cleaning Plugging PTP	Tanker	158475	Johor PTP
336	28.1.19	Bunga Laurel	SQ000379-Bunga Laurel - Propellor polishing @ Bintulu, Sarawak , Malaysia anchorage	Tanker	11908	Bintulu
335	28.1.19	Sevan Driller	Manpower supply for Sevan Driller	Semisubmersible	-	KSB
334	25.1.19	PP101	Rope Access Team to for Port Leg Collision Check on PP101	Jack Up	-	MIRI
333	23.1.19	MS 1	To supply storage tank c/w sling to MS 1	Semisubmersible	-	Labuan
332	22.1.19	FSU 2	To supply Aux Condenser Anode for FSU 2	Tanker	80510	Linggi Melaka
331	22.1.19	FSU 1	To supply Aux Condenser Anode for FSU 1	Tanker	80510	Linggi Melaka
330	18.1.19	Sea Coral	SEA CORAL Loa 332 Class LRS UWILD/Anchor Entanglement Clearing at PTP	Tanker	156802	PTP Anchorage
329	17.1.19	Seadrill_Sevan Driler	Supply Transformer, Galley and Laundry Equipment to Sevan Driller	Semisubmersible	-	KSB East Wharf
328	15.1.19	CS PIONEER	CS PRIONEER SPOT CLEANING and CLASS IWS at PTP	Tanker	154159	PTP Anchorage
327	14.1.19	Hilong 106	Supply Oxygen and Acetylene for Hilong 106 at Johor Port	Pipe Laying Barge	-	Johor Port



326	9.1.18	Seri Cenderawasih	Supply Habitat System for LNG vessel_Seri Cenderawasih in Bintulu Anchorage	Tanker	133948	Bintulu Anchorage
325	7.1.18	Sevan Driller	Underwater Inspection and Unplugging work for Sevan Driller by Diver	Semisubmersible	-	Ksb East Wharf
324	27.12.18	Ensco 67	Supply RA Team for the Removal of Intermediate Guide (Liner)	Jack Up	-	Lamongan Shorebase, Indonesia
323	28.12.18	SPM Mooring	Locate and inspect SPM chains	-	-	PTP Anchorage
322	25.12.18	Sevan Driller	Shop Fabricate and Site Installation for Monkey Ladder for Sevan Driller at East Wharf	Semisubmersible	-	East Wharf KSB
321	21.12.18	Sevan Driller	Accommodation Piping Upgrading for Sevan Driller	Semisubmersible	-	East Wharf KSB
320	19.12.18	Ensco 67	Replace 5 lgth of Jetting Line for All Legs for Ensco 67 at Lamongan Shore base, Indonesia	Jack Up	-	Lamongan Shorebase, Indonesia
319	17.12.18	MV Molly Schulte	MV Molly Schulte Loa 189M UW Inspection Port Klang Malaysia	Cargo	27279	Port Klang Anchorage
318	16.12.18	LNG PUTERI DELIMA	LNG PUTERI DELIMA Uw Blanking/Plugging DN 65 Bintulu	Tanker	94430	Bintulu
317	12.12.18	Ensco 67	Crack repair at Bay 1 for all 3 legs for Ensco 67 at Lamongan Shore base, Indonesia	Jack Up	-	Lamongan Shorebase, Indonesia
316	12.12.18	Ensco 67	Replace 1 lgth of Jetting Line for STBD Legs for Ensco 67 at Lamongan Shore base, Indonesia	Jack Up	-	Lamongan Shorebase, Indonesia
315	5.12.18	Ensco 67	Supply Rope Access Team to paint the leg mark for all three leg until approximate bay 20	Jack Up	-	Lamongan Shorebase, Indonesia
314	4.12.18	Sevan Driller_Epic	Supply 15k PSI HPWJ Machine for Thruster Cleaning	Semisubmersible	-	East Wharf KSB
313	1.12.18	Puteri Zamrud	Puteri Zamrud IWS	Tanker	86205	Bintulu
312	30.11.18	Seri Ayu	Seri Ayu IWS and Propeller Polishing	Tanker	95729	Bintulu
311	28.11.18	Sevan Driller_Epic	Manpower supply for Sevan Driller	Semisubmersible	-	East Wharf KSB



310	28.11.18	Ensco 115	Hull Plate Renewal Inside Preload Tank #S20 for Ensco 115 at Johor Port	Semisubmersible	-	Johor Port
309	28.11.18	Sevan Driller_Epic	Supply Pipe Spool and Blind Flange to Sevan Driller	Semisubmersible	-	East Wharf KSB
308	24.11.18	CMA CGM PUCCINI	CMA CGM PUCCINI Full hull Cleaning at Port Klang	Cargo	65730	Port Klang Anchorage
307	24.11.18	TOVE MAERSK	TOVE MAERSK Surface Cleaning of Oil Stains at Hull at Port Klang	Cargo	16982	Port Klang Anchorage
306	23.11.18	CS PROSPERITY	CS PROSPERITY Full Hull Cleaning/Class IWS PTP	Tanker	157863	PTP Anchorage
305	21.11.18	Sevan Driller, EPIC	Underwater Inspection for Thruster, Plugging and Unplugging work for Sevan Driller	Semisubmersible	-	KSB East Wharf
304	21.11.18	PUTERI ZAMRUD SATU	PUTERI ZAMRUD SATU Prop Polishing Bintulu (put through from Seaocean)	Tanker, Hazardous D	94446	Bintulu
303	20.11.18	M/T Minerva Marina	M/T Minerva Marina : hull cleaning @ Malaysia Sungai Linggi 18/11	Tanker	81467	Linggi , Melaka
302	20.11.18	Senibong	Assist Cable Landing Senibong Area	-	-	Senibong, JB
301	16.11.18	Ensco 67	Supply RA Team for the Intermediate Guide (Liner) installation	Jack Up	-	Lamongan Shorebase, Indonesia
300	16.11.18	Naga 2	Seabed Survey by Diver for Naga 2 at KSB Basin	Jack Up	-	KSB Basin
299	15.11.18	SFL YUKON	SFL YUKON Loa 189m Class IWS Kuantan Malaysia	Cargo	33044	Kuantan Port
298	14.11.18	CARL OLDENDORFF	CARL OLDENDORFF Class DNV GL UWILD Port Dickson	Cargo	51253	Port Dickson
297	10.11.18	EPIC MARine	Diamond Wlre Cutter	-	-	Workshop
296	10.11.18	MT DOver	MT DOVER Loa 333m Class IWS Batu Pahat Malaysia (including UTG)	Tanker, Hazardous C	160576	Batu Pahat
295	6.11.18	FSU 2	Design, Fabricate, Site Installation and Commisioning for FSU 2 - JRU Water Supply Project	Tanker	80510	Melaka
294	6.11.18	EPIC Marine	Lost Anchor Recovery KSB Basin	-	-	KSB Basin
293	4.11.18	MV Equanimity	MV Equanimity Blanking 3 x gratings OPL Port Klang	others	2999	Port Klang



292	2.11.18	Puteri Zamrud	PUTERI ZAMRUD SATU UWI and Prop Polishing Bintulu (put through from Seaocean)	Tanker, Hazardous D	94446	Bintulu
291	4.11.18	VOULA SEAS	Class Rina IWS Port Klang OPL	Cargo	17431	Port Klang OPL
290	1.11.18	Ensco 67	Intermediate UWILD and Upper Guide Replacement for ENSCO 67	Jack Up		Lamongan Shorebase, Indonesia
289	29.10.18	GC FUZHOU	Uw HC Vertical Side Shell	Tanker	166223	Linggi, Melaka
288	14.10.18	FSU 2	Renewal of Scupper Saver & Drain Pipe Inside Engine Room Renewal for FSU 2 at Linggi, Melaka Malaysia	Tanker	80510	Melaka
287	14.10.18	FSU 2	Renewal of Mast Stay Wire and Securing Arrangement for FUS 2	Tanker	80510	Melaka
286	14.10.18	FSU 1	Additional for Mast Stay Wire and Securing Arrangement for FUS 1	Tanker	80510	Melaka
285	13.10.18	MV NORD BELUGA	MV NORD BELUGA Loa 229m UWI Fouling and Propeller Polishing Kuantan Port	Cargo	- 43729	Kuantan Port
284	9.10.18	Ensco 67	Supply Gusset Plate #3 and Replace Gusset Plate #3 in all Legs for Ensco 67 at Lamongan Shore base, Indonesia	Jack Up		Lamongan Shorebase, Indonesia
283	8.10.18	Winson 5	Winson 5 Manual Sea Chest Grating Cleaning at PTP	Tanker	163761	PTP
282	4.10.18	Wan Hai 305	WAN HAI 305 CLEARING OF ANCHOR ENTANGLEMENT OPL PASIR GUDANG LAT 1-18.6N LON 104-7E MALAYSIA	Cargo	26681	Port Klang Anchorage
281	4.10.18	SBI Lambada	SBI LAMBADA Class Rina IWS Port Klang	Cargo	43301	OPL Pasir Gudang
280	3.10.18	FSU 2	Supply Cargo Valve Handle for FSU 2 at Linggi, Melaka Malaysia	Tanker	80510	Melaka
279	3.10.18	FSU 1	Supply Cargo Valve Handle for FSU 1 at Linggi, Melaka Malaysia	Tanker	- 80510	Melaka
278	28.9.18	Ensco 115	TO SUPPLY NYLON GREEN CANVAS 10FT X 10FT	Jack Up		Johor Port



277	18.9.18	Ensco 67	To Provide EH 36 Gusset Plate for Ensco 67	Jack Up		Lamongan Shorebase, Indonesia
276	10.9.18	Ensco 67	Supply MPI Inspector complete with MPI Yoke for Gusset Plate Inspection on Ensco 67	Jack Up		Lamongan Shorebase, Indonesia
275	9.9.18	LNG GRACE ENERGY	LNG GRACE ENERGY Loa 272m Inspection for Blanking Linggi	LNG Tanker	107146	Linggi Melaka
274	6.9.18	CC TITUS	CC TITUS Class BV IWS PTP anch	Container Ship	90931	PTP Anchorage
273	1.9.18	Ensco 67	To Supply Rope Access Team for UTG Inspection for Gusset Plate onboard Ensco 67	Jack Up	-	Lamongan Shorebase, Indonesia
272	30.8.18	Mopu Sepat	Clamp Removal for Mopu Sepat at KSB Wharf by Diver	Converted Jack Up	- -	KSB Wharf
271	28.8.18	FSU 1	Renewal of mast stay wire and securing arrangement for FUS 1	Tanker	- 80510	Linggi Melaka
270	20.8.18	LNG SERI BAKTI	Propeller Polishing Miri (put through by Seaocean diving)	Tanker	105335	Miri Anchorage
269	14.8.18	FSU 2	To Provide Service to Calibrate and Issue Certificate for 15ppm bilge Alarm Monitor and Dewpoint Digital Meter (Tenaga Empat)	Tanker	80510	Linggi Melaka
268	14.8.18	FSU 1	To Provide Service to Calibrate and Issue Certificate for 15ppm bilge Alarm Monitor and Dewpoint Digital Meter (Tenaga Satu)	Tanker	- 80510	Linggi Melaka
267	13.8.18	Jade PROSPER	Jade Prosper Manual Cleaning for propeller and sea chests at Linggi	Tanker	160220	Linggi Melaka
266	10.8.18	FSU 1	Shop Fabricate Gangway Base Platform for FSU 1	Tanker	80510	Linggi Melaka
265	6.8.18	West Orion	Underwater Inspection for 11nos Anchors for West Orion at West Wharf KSB	Semisubmersible Rig	-	KSB West Wharf
264	1.8.18	JADE PROSPER	JADE PROSPER Uw Inspection Linggi No Class	Tanker	160220	Linggi, Melaka
263	31.7.18	MV Sonangol Kalandula	MV Sonangol Kalandula LOA 274 Propeller Polishing, Seachest cleanging and IWS at KSB Wharf, Malaysia	Tanker	83753	KSB Wharf



262	31.7.18	Naga 7	Seabed Survey by Diver for Naga 7 at KSB Basin	Jack Up	-	KSB West Wharf
261	30.7.18	Sevan Driller	Blasting and Painting Project for Sevan Driller and West Orion at KSB Wharf	Semisubmersible Rig	-	KSB East Wharf
259	27.7.18	UBC CHILE	UBC CHILE Loa 132 M Class DNVGL Langkawi	Cargo	8559	Langkawi
258	27.7.18	Majulah Singapore	MV Majulah Singapura LOA 186 UW Inspection No Class Port Klang Anchorage Malaysia	Cargo	32296	Port Klang
257	27.7.18	Naga 7	Underwater Temporary Crack Repair for Naga 7 at KSB West Wharf	Jack Up		KSB West Wharf
256	14.7.18	Mv ECOMAR G.O.	Class BV IWS Kuantan anchorage	Bulk Carrier	75093	Kuantan Anchorage
254	12.7.18	Ensco 67	Gusset Plate Inspection for Ensco 67 in Indonesia	Jack Up		Lamongan Shorebase, Indonesia
253	12.7.18	Naga 7	Removal of Support Structure for Naga 7 at KSB West Wharf	Jack Up		KSB West Wharf
252	12.7.18	FSU 2	SSL Optical Link Replacement for FSU 2	Tanker	80510	Melaka
251	3.7.18	SBM 5 Miri	Rental of Bathycorrometer on behalf of Seaocean SBM5 Job	-	-	Miri
250	7.7.18	Ocean GreatWhite	HULL Inspection for Ocean Great White at Labuan Anchorage	Semisubmersible Rig	-	Labuan Anchorage
249	25.6.18	MV DAIWAN WISDOM	MV DAIWAN WISDOM Loa 167 DNVGL IWS Port Klang	Cargo	- 19825	Port Klang OPL
248	22.6.18	Mopu Sepat	Clamp Removal for Mopu Sepat at KSB Anchorage	Converted Jack Up		Kemaman Anchorage
247	21.6.18	FSU 2	Replacement for CTMS Tank 5 Coaxial Cable 10 Core for FSU 2	Tanker	80510	Melaka
246	21.6.18	Naga 7	Rental of Gangway for Naga 7 at West Wharf, KSB	Jack Up	-	KSB West Wharf
245	20.6.18	COSL POWER	Supply Auger Spare Part for Rig COSL POWER	Jack Up	-	Labuan Anchorage



244	20.6.18	Naga 7	ABS UWILD – Intermediate Survey RIG UMW Naga 7 – Location KSB Wharf	Jack Up		Labuan Anchorage
243	18.6.18	COSL POWER	Accommodation Repair for COSL POWER	Jack Up	-	Labuan Anchorage
242	8.6.18	COSL POWER	Convert Lifting Sub from GPXT39 Pin to NC38 Pin Standard for COSL POWER at Labuan Anchorage	Jack Up	-	Labuan Anchorage
241	6.6.18	MV TAIBAH	Plugging 2in Ob discharge	Tanker	- 28981	Off Desaru
240	30.5.18	NAGA 7	Sea bed survey in preparation for rig coming in	Jack Up		KSB West Wharf
239	24.5.18	FOIS NAUTICA TEMBIKAI	To provide 2 pax UTG Technician for FOIS Nautica Tembikai at Offshore Terengganu	Tanker	- 28433	Offshore Terengganu
238	22.5.18	UMW Naga 3	Intermediate UWILD for Naga 3	Jack Up	-	Labuan Anchorage
237	22.5.18	MOPU SEPAT	Diving Operation Afloating MOPU Sepat at Kemaman Anchorage	Converted Jack Up	- -	Kemaman Anchorage
236	15.5.18	MV SINOMERCHANT	Class KR Uw Inspeccion for Grounding Lumut	Cargo	155051	Lumut Anchorage
235	15.5.18	PVD 3	To provide Service Engineer for Lifteraft Davit Annual Inspection for PVD 3	Jack Up	-	Offshore Terengganu
234	12.5.18	Hilong 106	Supply PVC Fittings and Check Valve for Hilong 106	Pipe Laying Barge	-	Johor Port
233	19.6.18	FSU 2	Accommodation Refurbishment for Master Cabin and ECR Room for FSU2	Tanker	- 80510	Melaka
232	19.6.18	FSU 2	Accommodation Refurbishment for FSU2	Tanker	80510	Melaka
231	19.6.18	FSU 1	Accommodation Refurbishment for Master Cabin and ECR Room for FSU1	Tanker	80510	Melaka



230	19.6.18	FSU 1	Accommodation Refurbishment for Office/Galley for FSU1	Tanker	- 80510	Melaka
229	12.5.18	FELIXSTOWE BRIDGE	FELIXSTOWE BRIDGE Loa 294M CLASS IWS PORT KLANG	Cargo- Hazard A	54809	Port Klang
228	10.5.18	Hilong 106	Supply Fitter and Carpenter for Hilong 106	Pipe Laying Barge	-	JB to Indonesia
227	8.5.18	FOIS NAUTICA TEMBIKAI	UWILD for FOIS NAUTICA TEMBIKAI- Offshore Terengganu BV Class	Tanker	28433	Offshore Terengganu
226	5.5.18	MOPU SEPAT	Diving Operation for MOPU Sepat at Kemaman Anchorage	Converted Jack Up		Kemaman Anchorage
225	5.5.18	Sydney Spirit	Class LRS UW Inspection for grounding damage	Tanker	81326	Kemaman
224	3.5.18	Ever Diamond	Install Sandwich Plate Port Klang OPL	Cargo- Hazard D	52090	Port Klang, OPL
223	2.5.18	GAS NEMISIS II	Blanking SC, Cleaning SC & hull photos Kemaman Port	LPG Tanker	3678	Kemaman Port
222	28.4.18	COSL POWER	Annulus Line for COSL Power	Jack Up		Labuan Anchorage
221	26.4.18	Hilong 106	To Supply PVC Material for Hilong 106	Pipe Laying Barge	-	Tok Bali
220	24.4.18	MT PURE 1	Spot cleaning, propeller / sc cleaning Linggi	Tanker	1973	Linggi, Melaka
219	24.4.18	ENSCO 8504	Rope Access to Clean/Paint the Burnt Areas on Ensco 8504	Jack Up		Singapore OPL
218	18.4.18	Ocean GreatWhite	To Supply 2 Pax Certified Inspector to perform Ultrasonic Thickness Gauging (UTG) of all piping or APV's onboard Ocean GreatWhite	Semisubmersible Rig	-	Labuan Anchorage
217	18.4.18	MV GRAND TAJIMA ONE (old name:WHITE MIYABI).	MV White Miyabi Class NK In-Water Survey at Penang, Malaysia	Tanker	9593	Penang Anchorage
216	16.4.18	Hilong 106	To supply GP 328V Walkie Talkie and Battery HNN 9010 for GP328V	Pipe Laying Barge	-	Tok Bali



215	13.4.18	COSL POWER	Supply Manpower for Auger Shaft Extension on Rig COSL POWER	Jack Up		Labuan Anchorage
214	9.4.18	Tag Nur 1,2,3 & 20	Tag Nur 1,2,3 & 20 LOA 30mtr Class BV In-Water Survey at Linggi Melaka, Malaysia	Tug	-	Linggi, Melaka
213	28.3.18	Naga 2	UWILD CLASS DNV Brunei Bay Labuan	Jack Up		Labuan Anchorage
212	21.3.18	PVD 3	To provide 1 MPI Inspector c/w equipment for Stbd side Cantilever hold down inspection	Jack Up		KSB
211	15.3.18	PVD 3	Fixed CO2 System Testing and Hydro-Test, rental of bottle and flexible hose	Jack Up		KSB
210	14.3.18	FSU 1 and FSU 2	Non-Cryogenic E&I Calibration c/w hand tools for FSU 1 and FSU 2	Tanker	80510	Melaka
209	14.3.18	CS Prosperity	Cofferdam Operation	Tanker	157863	PTP
208	13.3.18	Molly Schulte	Uw inspection Port Klang OPL	Cargo, Hazardous Category A	- 27279	Port Klang
207	11.3.18	Naga 4	Provide Load Test to Delta Plate	Jack Up	-	KSB West Wharf
206	7.3.18	PVD 3	Supply NDT technicians for Drilling Equipment	Jack Up	-	KSB Basin
205	6.3.18	CosL Power	HP Nud Line Replacement	Jack Up		Labuan
204	3.3.18	Ken Wave	Rudder Drilling, grinding and welding works	Cargo	31759	Johor Port
203	3.3.18	Maritime Jewel	Inspection for fouling Tg Bruas	Tanker	157833	Tg Bruas
202	24.2.18	PVD 3	Seabed Survey for PVD III at KSB Basin (Departure)	Jack Up		KSB Basin
201	23.2.18	PVD 3	Rental of Gangway for PVD III at East Wharf, KSB	Jack Up		KSB Basin
200	23.2.18	Aquamarine Driller	Rental of Mooring Rope to Aquamarine Driller at KSB West Wharf	Jack Up		KSB Basin
199	23.2.18	Aquamarine Driller	Rental of gangway to Aquamarine Driller at KSB West Wharf	Jack Up		KSB West Wharf



198	23.2.18	FSU 1 and FSU 2	Installation of lathe machine and bandsaw machine	Tanker	80510	Melaka
197	20.2.18	Naga 4	Seabed Survey for Naga 4 at West Wharf 300 to 410 berth mark	Jack Up		KSB West Wharf
196	20.2.18	PVD III	Annual Survey (LB/PRV/Gauges) for RIG PV DRILLING III	Jack Up		KSB East Wharf
195	20.2.18	Naga 4	Five Yearly Maintenance Works for Naga 4	Jack Up	-	KSB West Wharf
194	20.2.18	PVD III	Annual LGI and Drop Inspection for RIG PVD III	Jack Up	-	KSB East Wharf
193	14.2.18	PVD VI	Seabed Survey for PVD VI at KSB Basin (Arrival)	Jack Up		KSB Basin
192	14.2.18	PVD III	Seabed Survey for PVD III at KSB Basin (Arrival)	Jack Up	-	KSB Basin
191	14.2.18	Aquamarine Driller	Seabed Survey for Aquamarine Driller at KSB Basin	Jack Up		KSB Basin
190	14.2.18	MV Ken Wave	MV KEN WAVE Class NK IWS, Grinding and Welding Works Port Klang	Cargo	- 31759	Port Klang
189	14.2.18	THOR ENDEAVOUR	Class NK IWS Pasir Gudang	Cargo	- 25676	Pasir Gudang
188	30.1.18	MV WAVE FRIEND	MV WAVE FRIEND Class NK IWS Langkawi	Cargo	- 17018	Langkawi
187	29.1.18	Sea Latitude	MT Sea Latitude Propeller Polishing and Manual Seachest Cleaning and Hull Cleaning	Tanker	- 157883	Linggi
186	25.1.18	PVD VI	ABS UWILD – Intermediate Survey RIG PV DRILLING VI – Location KSB Wharf	Jack Up	-	KSB East Wharf
185	25.1.18	PVD III	ABS UWILD – Intermediate Survey RIG PV DRILLING III – Location KSB Wharf	Jack Up		KSB East Wharf
184	24.1.18	CS Brilliance	CS Brilliance CLASS LRS IWS Batu Pahat MALAYSIA	Tanker	159423	Batu Pahat
183	19.1.18	KPV Redang	KPV REDANG Uw Blanking Works Labuan Shipyard	Tug	3719	Labuan Shipyard



182	16.1.18	Northern Star	Northern Star Propeller Polishing & Rudder Manual Scrapping PTP Anch	Tanker	149407	PTP Anchorage
181	25.1.18	Aqua Marine	Aqua Marine USILW at KSB	Jack Up		KSB West Wharf
180	16/1/18	MV Yu Hong	MV TBN Loa 229m draft 14m full hull cleaning PTP (Yu Hong)	Cargo	43974	PTP Anchorage
179	14/1/18	MT Marine Star	MT Marine Star Propeller Polishing and Manual Seachest Cleaning	Tanker	158475	Melaka
178	10/1/18	MT Marine Star	Load Testing services for MT Marine Star	Tanker	158475	Melaka
177	8/1/18	Hakuryu 5	Fill or Patch Weld On Bruce Chaser Ring for Hakuryu 5	Semisubmersible Rig	-	Labuan
176	3/1/18	Sevan Driller	Modification and repair for tower gangway	Semisubmersible Rig	-	KSB East Wharf
175	2/1/18	Ocean Onyx	Welding Crew for Ocean Onyx	Semisubmersible Rig	-	Labuan
174	30/12/17	Lewek Conqueror	5ft Partial Manual Cleaning and Manual Seachest Cleaning for Lewek Conqueror	Accommodation barge	10196	Labuan
173	29/12/17	Ocean Onyx	Rig Positioning Services for Ocean Onyx at Labuan Anchorage	Semisubmersible Rig	-	Labuan
172	27/12/17	JUBILEE STAR	JUBILEE STAR Class ABS UWILD PTP	Tanker	164371	PTP Anchorage
171	19/12/17	HAKURYU-5	To provide 2 pax UTG Technician for Hakuryu 5 at Labuan Anchorage	Semisubmersible Rig	-	Labuan
170	19/12/17	SIEM GARNET	Class DNVGL IWS Labuan	Tug Boat	7473	Labuan
169	15/12/17	MV PORT KLANG	Uw Insp, Clean SC & Remove entanglement	Cargo, Hazardous Category A	14278	Port Klang
168	14/12/17	KSB Offshore	Rental of 60ft Gangway for BSSB	-	-	KSB Offshore
167	14/12/17	AMITY STAR	CLASS LRS UWILD PTP ANCHORAGE	Tanker	156336	PTP Anchorage
166	11/12/17	MV KORALIA	Blanking sc and valve change out Langkawi	Cargo	5929	Langkawi / Tg Bin



165	6/12/17	Hilong 106	To supply Steel for Jacket Levelling Frame (PR-0028)	Pipe Laying Barge	-	Johor Port
164	4/12/17	HAKURYU-5	RA Access Painter for ROPE ACCESS Draft Mark Painting	Semisubmersible Rig	-	Labuan
163	4/12/17	MTT Port Klang	DNV GL IWS Port Klang	Cargo, Hazardous Category A	14278	Port Klang
162	28/11/17	HAKURYU-5	JDC Accommodation Refurbishment	Semisubmersible Rig	-	Labuan
161	23/11/17	Hilong 106	Supply material for USBL Pole and Davit for Hilong 106 (PR 0017)	Pipe Laying Barge	-	Johor Port
160	22/11/17	MV Da Zi Yun	MV DA ZI YUN (LOA 166M) CLASS CCS IN-WATER ISURVEY PORT KLANG MALAYSIA	Cargo	20949	Port Klang
159	22/11/17	Tenaga Satu and Tenaga Empat	Supply of New CHINA "BAOJI" Brand Lathe Machine for FSU 1 at Linggi Melaka, Malaysia	Tanker	80510	Melaka
158	22/11/17	Tenaga Satu and Tenaga Empat	Supply New Taiwan Brand "WAY TRAIN" Horizontal Band Saw Machine for FSU 1 at Linggi Melaka, Malaysia	Tanker	80510	Melaka
157	16/11/17	West Orion	Seabed Survey for West Orion	Semisubmersible Rig	-	KSB Basin
156	16/11/17	Ocean Onyx and Ocean Apex	Seabed Clearance Survey at Labuan Anchorage, Malaysia	Semisubmersible Rig	-	Labuan
155	16/11/17	FSU 2	Additional Work	Tanker	80510	Melaka
154	15/11/17	Hlong	Linepipe loadout	Pipe Laying Barge	-	Kuantan
153	15/11/17	Ensco 106	Supply Manpower to follow tow from Singapore to Indonesia	Jack Up Rig	-	Singapore
152	3/11/17	MISC	Tenaga Empat	Tanker	80510	Melaka
151	2/11/17	HAKURYU-5	JDC UWILD WorkScopes	Semisubmersible Rig	-	Labuan
150	2/11/17	Hailong 106	Supply QC Inspection tools to Hilong 106	Pipe Laying Barge	-	Johor Port



149	31/10/17	Hailong 106	Hilong 106 Misc Items for Structure PR 006	Pipe Laying Barge	-	Johor Port
148	31/10/17	Saipem Karimun	Saipem Karimun Yard Wharf Inspection	-	-	Karimun
147	29/10/17	AOM 1847	Barge AOM 1847 Class Rina IWS Tg Setapa Johor	Barge	-	Tg Setapa Johor
146	27/10/17	FSU 2	Various Area Repair (Wasted Plate, Railing and Pipe) on Deck for Tenaga Empat	Tanker	80510	Melaka
145	27/10/17	FSU 2	Fire Line Spool Fabrication and Installation at Accommodation Entrances for Tenaga Empat at Linggi Melaka, Malaysia	Tanker	80510	Melaka
144	27/10/17	Pacific Valour	To perform OVID inspection for vessel Pacific Valour	Tug	2147	Singapore
143	18/10/17	MISC Tenaga Satu	Calibration and Issue Certificate for 15ppm Bilge Alarm Monitor	Tanker	80510	Melaka
142	12.10.17	Mineral Subic	Mineral Subic Change of Speed log Lumut	Cargo	93695	Lumut
141	12/10/17	Hilong 106	Supply Material to Hilong 106	Pipe Laying Barge	-	Johor Port
140	10/10/17	Tenaga Satu	AC REpair onboard FSU1-MISC	Tanker	80510	Melaka
139	6/10/17	PP101	Perisai Drilling Sdn Bhd - PP101 Side Scan Sonar	Jack Up Rig	-	KSB Anchorage
138	26/9/17	COOEC-MV Berly	To remove Sea fastening on MV Berly at AsiaFlex Yard	Barge	-	Tg Langsat
137	18/9/2017	Tenaga Empat	Calibration and Issue Certificate for 15ppm Bilge Alarm Monitor	Tanker	80510	Melaka
136	15/9/17	MT PURE 1	MT PURE 1 Class SCM IWS LINGGI MALAYSIA	Tanker	1973	Linggi, Melaka
135	14/9/17	Ensco TBA	To perform OVID inspection for vessel	-	-	Singapore



134	13/9/17	Tenaga Satu and Tenaga Empat	Weldment Repair for Tenaga Satu and Tenaga Empat	Tanker	80510	Melaka
133	11/9/17	Orient King / Splendor Taipei	Class NK IWS PEnang - Change name to Splendor Taipei	Cargo	7506	Penang
132	5/9/17	CS INnovation	CS Innovation Class BV IWS at PTP anchorage	Tanker	156692	PTP Anchorage
131	29/8/17	Ensco 106	Re-Program EPIRD	Jack Up Rig	-	Labuan
130	26/8/17	COOEC - Towage & Semi-Submersible Fleet Division	Sea Fastening Works for Guangzhou Salvage in Asia Flex / KSB	Semisubmersible Rig	-	AsiaFlex Tg Langsat
129	25/8/17	Chios 01	class RINA UW inspection Pasir Gudang	Tanker	81315	
128	21/8/17	IVS PHINDA	thereafter IWS)	Cargo	23224	Kuantan
127	15/8/17	SEA EQUATORIAL	CLASS LRS UWILD LINGGI - UMC INTL Jason	Tanker	156880	Linggi
126	8/8/17	Tenaga Satu	Calibration and Issue Certificate for 15ppm Bilge Alarm Monitor	Tanker	80510	Melaka
125	8/8/2017	Orient Orchid	MV ORIENT ORCHID SURFACE WELDING OF RUDDER COVER PLATE AT PRAI ANCHORAGE OR PORT	Cargo	31217	Prai Port
124	5/8/2017	Star Bright	STAR BRIGHT CLASS LR IWS PTP MALAYSIA	Tanker	158475	PTP Anchorage
123	3/8/2017	Ensco 106	Piping repair during on tow to Singapore from Miri	Jack Up Rig	-	Miri
122	1/8/2017	PP101	Span Breaker repair	Jack Up Rig	-	MIRI / KSB
121	27/7/2017	PP101_EPIC	Anchor Recovery for PP101 at KSB	Jack Up Rig	-	KSB Basin
120	19/7/2017	Sevan Driller_Epic	Blanking Job for Sevan Driller at KSB East Wharf	Semisubmersible Rig	-	KSB East Wharf
119	17/7/2017	EPIC_Naga 5	Seabed survey for Naga 5 at KSB anchorage for 200m x 200m using side scan sonar and magneto	Jack Up Rig	-	KSB Anchorage



118	11/7/2017	Marine Star	MARINE STAR CLASS LR IWS PTP MALAYSIA - Southernpec (Singapore) Shipping Pte Ltd	Tanker	158475	PTP Anchorage
117	30/6/2017	Ensco 106	Supply engineer and technician to Ensco 106 for Engine Alignment	Jack Up Rig	-	Offshore, Miri
116	28/6/2017	MV Comatce Sun (NK Class)	IWS for MV Comatce Sun Class NK	Cargo	14431	Port Klang Anchorage
115	22/6/2017	UMW	Diverter Housing Modificaiton	Jack Up Rig	-	Workshop
114	21/6/2017	San Hang Tong	Class CCS In-water survey	Tug	-	Kuantan
113	21/6/2017	Seven Driller (EPIC)	Seabed survey at KSB East Wharf KSB for Seven Driller	Semisubmersible Rig	-	KSB
112	19/6/2017	MISC Mr Rohit	MISC LNGC TBA In-water survey Bintulu	Tanker	86205	Bintulu
111	13/6/2017	Seven Driller (EPIC)	Gangway analysis and fabrication	Semisubmersible Rig	-	Workshop
110	29/5/2017	Maran Callisto	VLCC Maran Callisto UW Hull cleaning Linggi	Tanker	157833	Linggi
109	23.5.17	Ensco 106	Cargo Basket, Container and Gas Rack Inspection for ENSCO 106	Jack Up Rig	-	KSB Yard
108	20.5.17	Ensco 106	Supply Scaffolder and Material for Scaffold Erection at Engine Room and Air Compressor Room	Jack Up Rig	-	Offshore Terengganu
107	21/5/2017	AS Savonia	AS Savonia Sandwich Doubler temporary Repair Port Klang	Cargo	16850	OPL Port Klang
106	20/5/2017	Tenaga 1 and Tenaga 4	UWILD for Tenaga 1 and Tenaga 4 (MISC)	Tanker	80510	Melaka
105	16/5/2017	Cape Fortius	Vessel TBA UW Welding of doubler or sandwich doubler installation PTP Anchorage (Cape Fortius)	Cargo	24720	PTP anchorage
104	11/5/2017	MV Jade Palm	Jade Palm blanking works at PTP anchorage	Tanker	156802	PTP anchorage
103	11/5/2017	Seven Driller (EPIC)	Fabricate and Install Fender in East Wharf for Seven Driller, KSB	Semisubmersible Rig	-	Workshop
102	8/5/2017	MV Speranza	UWILD for MV Speranza under Class LR	Tanker	158475	PTP Anchorage



101	15/5/2017	CS Development	UWILD for CS Development under Class BV	Tanker	163720	PTP Anchorage
100	7/5/2017	MT ELBRUS	Class DNV GL In Water Survey at Linggi	Tanker	29327	Linggi
99	2/5/2017	Seven Driller (EPIC)	Design of Gangway Tower and Gangway for Seven Driller	Semisubmersible Rig	-	Workshop
98	24/4/2017	Seven Driller (EPIC)	Designing the fender support for Seven Driller	Semisubmersible Rig	-	Workshop
97	20/4/2017	CS Development	Class BV IWS Survey for CS Development	Tanker	163720	OFF PTP Malaysia
96	20/4/2017	Eagle Vermont	Eagle Vermont Blanking Job at Linggi	Tanker	161233	Linggi Melaka, Malaysia
95	19/4/2017	MT Chang Young	MT Chang Young Blanking Job at Tg Bin Anchorage	Tanker	8448	PTP / Tg Bin Anchorage
94	18/4/2017	Ensco 106	Burner Boom Modification for ENSCO 106	Jack Up Rig	-	Offshore Terengganu
93	17/4/2017	MV Densa Whale	Plugging Job at Linggi (TnT)	Tanker	81186	Linggi
92	13/4/2017	COSL Seeker	Supply Auger to COSL Seeker	Jack Up Rig	-	Labuan
91	15.4.2017	Chuan Hong 68	CCS IWS	Tug	8352	Kuantan Port
90	10.4.2017	PP101	Supply scaffolder to assist rig in scaffold erection	Jack Up Rig	-	Terengganu Offshore
89	11.4.2017	Christa Schulte	Class DNV GL CCTV IWS	Cargo	51872	PTP Anchorage
88	2.4.2017	ENDEAVOUR	CLASS BV IWS	Cargo	27927	Johor Port
87	20.3.2017	PP101	Lump Sum cost for STBD side Helideck Fire Monitor Platform and stairway	Jack Up Rig	-	KSB Offshore
86	20.3.2017	UMW NAGA 5	UWILD and Debris Survey (alongside and anchorage)	Jack Up Rig	-	KSB West Wharf
85	14.3.2017	Sinking Boat	Dive team to mark the wreck at PTP	-	-	PTP Port Limit
84	25.2.2017	Barge Sinaran Pelangi	CCTV inspection and salvage job	Barge	-	Kuala Terengganu
83	25.2.2017	MV Hayling Island	CCTV Inspection and Paint samples	Cargo	28927	PTP Wharfside



82	21.2.2017	EPIC	Seabed clearance survey 1000m x 2000m at KSB	-	-	KSB West Wharf
81	19.2.2017	LGC Debbie	NK Class IWS	Tanker	3419	OPL Penang
80	18.2.2017	Tag Nur 9	Propeller polishing, sea chest cleaning and clear entanglement	Tug	-	Linggi Melaka
79	10.2.2017	Maersk Cabo Verde	CCTV IWS and Oil Spill Cleaning	Cargo	50869	PTP Anchorage
78	10.2.2017	Yangtze Star	Propeller Polishing	Tanker	147012	Linggi Melaka
77	2.2.2017	Maran Callisto	IWS with still photography	Tanker	157833	Linggi Melaka
76	27.1.2017	Yangtze Star	Hull Cleaning	Tanker	147012	Linggi Melaka
75	21.1.2017	UMW Naga 4	Debris Survey by Diver	Jack Up Rig	-	KSB West Wharf
74	14.1.2017	APL Denver	Temporary repair after the collision incident for her to go shipyard	Cargo	43071	Johor Port
73	9.1.17	Stolt Tsubaki	Oil Stains cleaning by HP water jetting	Tanker	7242	Pasir Gudang OPL
72	9.1.17	MV Hyundai Treasure	KR Class IWS	Cargo	28171	OPL Penang
71	8.1.2017	MV Red Diamond	CCTV Inspection / Propeller polishing	Cargo	32637	OPL Penang
70	5.1.2017	Alter Ego 1	CCTV inspection, SC cleaning, manual clearing of entanglement tailshaft reading and rudder pintle clearance	Tanker	160100	Linggi Melaka
69	2.1.2017	Maersk Sebarok	CCTV Inspection	Cargo	79702	PTP Wharfside
68	20.12.2016	UMW Naga 8	Structural Analysis for 10ton Winch Platform and 20 ton padeye platform	Jack Up Rig	-	-
67	22.12.2016	Ensco 56	Scaffolding erection for rig operation	Jack Up Rig		Tg Langsat Anchorage
66	20.12.2016	Ensco 106	Conductor platform modification and scaffolding	Jack Up Rig	-	Tg Langsat Anchorage



65	18.12.2016	UMW Naga 2	Seabed and debris survey by diver alongside wharf	Jack Up Rig	-	KSB West Wharf
64	17.12.2016	UMW Naga 4	Seabed and debris survey by diver at anchorage KSB	Jack Up Rig	-	KSB West Wharf
63	8.12.2016	Ensco 106	RA Team for UWILD top side inspection	Jack Up Rig	-	Tg Langsat Anchorage
62	12.12.2016	San Giorgio	IWS And Polishing	Cargo	20239	PTP Wharfside
61	Dec 2016	UMW Naga 4	a) Lifeboat platform replacement including remove damage lifeboat and davit b) Piping replacement/renewal and structural repair works Lighting and automation work	Jack Up Rig	-	West Wharf KSB
60	28.11.2016	Ensco 67	RA team for Aircraft warning light replacement (all 3 legs)	Jack Up Rig	6749	Johor Port
59	21.11.2016	Ensco 67	Air tugger installation at Drill Floor	Jack Up Rig	6749	Johor Port
58	18.11.2016	Ensco 67	Jet Lines Clamp installation (removal and welding) on all 3 legs by rope access	Jack Up Rig	6749	Johor Port
57	10.11.2016	T&T Salvage Asia	Bunker Vessel Flourish – Clearing Entanglement	Cargo	116396	PTP Wharfside
56	9.11.2016	Ensco 67	Leg Well Bulkhead renewal with NDT (ABS Class)	Jack Up Rig	6749	Johor Port
55	1.11.2016	Port	Laying the wave breaker blocks	-	-	Kuantan Port
54	30.10.2016	Energy Star	a) ABS Class UWILD b) Chain inspection c) Steel renewal	Tanker	164371	PTP Anchorage
53	26.10.2016	Ensco 67	Sheaves Replacement below CMC / below drill floor by using rope access	Jack Up Rig	6749	Johor Port
52	21.10.2016	Treatment Plant	Valve and pump change in treatment plant	-	-	KL
51	21.10.2016	EPIC	Seabed survey for Naga 8 at KSB	Jack Up Rig	-	KSB West Wharf



50	19.10.2016	Ensco 67	Unclogged Drains inside Accommodation Ensco 67 using HP and High Flow rate machine	Jack Up Rig	6749	Johor Port
49	19.10.2016	Ensco 67	Automation / Sensor Calibration for Ensco 67	Jack Up Rig	6749	Johor Port
48	17.10.2016	Sinaran Warna & Warni	Class UWILD	Tug Boat / Barge	217	PTP Anchorage
47	14.10.2016	Ensco 67	c) Site Shell cleaning and painting by Rope Access team with HP water jetting	Jack Up Rig	6749	Johor Port
46	23.9.2016	Yamato Spirit	ABS Class IWS	Tanker	60379	Melaka Anchorage
45	21.9.2016	DHT Leopard	CCTV Rudder & Propeller, Propeller Polishing	Tanker	154180	Linggi Anchorage
44	1.9.2016	Perisai Drilling Sdn Bhd	a) ABS Class UWILD b) Helideck's structural works repaired with 100 men team. c) Steel works on bulwark and hanging platform Seabed survey	Jack Up Rig	10501	West Wharf KSB
43	Aug 2016	PTP wharf	Oil Spill cleaning job with 60 plus divers and various type of equipment	Maersk Liner	-	PTP Wharf
42	Aug- Nov 2016	ENSCO 67	a) UWILD SPS #8 by ABS CLASS b) Cracks and gusset plates replacement by Rope Access 6G welders c) Jetting line clamp replacement d) Blasting and painting by R/A e) Unclogged drains by high pressure and high flow 10K pump f) Sensors calibration g) Navigational lights changed out by R/A h) Texas Deck refurbishment i) Steel renewal in preload tanks	Jack Up Rig	6749	Johor Port



			j) Tank cleaning k) Automation Scaffolding around the rig for rig operation			
41	25.8.2016	FPSO Opportunity	ABS IWS	Storage	96896	TG Langsung Johor
40	23.8.2016	MV Haris	Propeller polishing and CCTV inspection	Cargo	24528	PTP Wharf Side
39	17.8.2016	Shandong Zihe	Plugging discharge	Tanker	25400	OPL East Johor
38	29.7.16	MV Alabra	Propeller damage inspection and clear rope entanglement	Tanker	25669	PTP anchorage
37	19.7.16	ER France	d) Blanking Job for speed lock sensor	Cargo	66289	PTP wharf Side
36	15.7.16	MV Orea	CCTV Inspection with Propeller polishing	Cargo	24528	PTP wharf side
35	14.7.16	Industrial Royal	l) CCTV Stern Tube, clearing entanglements	Cargo	8963	OPL Desaru
34	12.7.16	Pacific Hope	Hull Cleaning	Cargo	17009	OPL Pasir Gudang
33	5.7.16	MV Leda	Inspection of Damage	Cargo	82100	Lumut Anchorage
32	1.7.16	MR 3311	ABS IWS Barge	Barge		Batam Indonesia
31	19.6.16	Newlead Albion	Full Hull Cleaning	Cargo	20954	Langkawi
30	31.5.16	SKS Tugela	Rope Entanglement	Cargo	72295	Off Kukup, Johor
29	20.5.16	Bonavia	Sea Chest Cleaning	Cargo	23691	Johor Anchorage
28	13.5.16	MV KAYA	CCTV inspection mainly on Thruster	Cargo	28616	PTP wharf side
27	11.5.16	MV CLIO	Digital Photography Inspection	cargo	15189	Lumut Anchorage
26	21.4.16	Maersk Mississippi	Digital Photography Insp/Polishing	Tanker	40268	PTP Anchorage
25	7.4.16	Trident Star	Class ABS IWS	Tanker	56365	Singapore
24	14.4.16	Casta Diva	Cofferdam Job Western OPL	Cargo	91373	Western OPL



23	14.4.16	Mv Waimea/Mv llenao	U/w Class DNV IWS/m. clean	Cargo	37031	Batam Barrilang
22	14.4.16	San Giorgio	U/w Class BV IWS/Polishing	Cargo	20239	PTP wharf side
21	22.3.16	MCC Java	U/w Class DNV IWS/UTG	Cargo	16915	PTP wharf side
20	21.3.16	Maersk Denpasar	U/w propeller trimming	Cargo	54675	PTP wharf side
19	6.3.16	MSC SOLA	Stern Tube CCTV Inspection	Cargo	131771	PTP wharf side
18	3.3.16	Awassi Express	Propeller Polishing	Cargo	24344	Western OPL
17	19.12.15	Olympic Loyalty II	Plugging discharge	Tanker	160046	Malacca anch
16	7.12.15	christa schulte	CCTV Paint Inspection	Cargo	52300	PTP wharf side
15	27.11.15	Maersk Stockholm	Plugging discharge	Cargo (Hazardous Category A)	91427	PTP wharf side
14	9.11.15	Mv Keno	Plugging discharge	Cargo	28616	PTP wharf side
13	5.11.15	Glory Pacific	Prop Polish	Cargo	10508	Johor Port
12	23.10.15	Fortune Star	Class LR IWS	Cargo	9575	PTP Anch
11	15.10.15	Maersk Sembawang	Cleaning Thruster & grating/tunnel	Cargo	79702	PTP wharf side
10	25.8.15	Northern Star	Side Shell Cleaning/Prop Polish	Tanker	149407	PTP
9	13.8.15	Mt Amity Star	UWILD	Tanker	156336	PTP
8	30.7.15	Mt Barnes	Hull Cleaning prop polish	Tanker	156802	PTP
7	22..7.15	Mt Amity Star	Scrapping Propeller/Rudder CCTV	Tanker	156336	PTP
6	1.5.15	Mv Glory River	Hull Cleaning prop polish	Cargo	12047	Johor Port
5	13-Apr-15	Mv Glory Pacific	Hull Cleaning prop polish	Cargo	10508	Johor Port

4	23-Feb-15	MSC Aurora	DNV UWILD PTP Wharfside	Cargo (Hazardous Category A)	143521	PTP wharf side
3	2-Feb-15	Glory River	IWS no Class, Prop Scrap	Cargo	12047	JP Wharfside
2	1-Dec-14	ER Stralsund	CCTV DNV/GL	Cargo	25630	PTP Anchorage
1	26-Nov-14	Luna Maersk	CCTV Rudder pintle	Cargo	50721	PTP wharf side

THE END

www.advantagemarine.com.my



ADVANTAGE MARINE
SERVICES (MALAYSIA) SDN BHD

REG No. 1110016-U
GST No. 00549990400

ANDREW TEOW

andrew.teow@advantagemarine.com.my
+65 8393 3227 | +60 16 448 8052

VICTOR WONG

sales@advantagemarine.com.my
+65 9789 3633 | +60 19 731 0016

DEREK SIOW

derek.siow@advantagemarine.com.my
+60 19 723 0016

MAIN OFFICE

No 27, Persisiran Laman Setia 7
Taman Laman Setia
Setia Business Park
81550 Johor Bahru
Malaysia

LABUAN BRANCH

SK, 0174, Kg Sungai Keling
Jalan Ranche-Ranche
P.O. BOX 80541
87015 F.T. Labuan, East Malaysia

KL BRANCH

Unit No. 1.3, 1st Floor, Surian Tower
No. 1, Jalan PJU 7/3, Mutiara Damansara
47810 Petaling Jaya, Selangor

